

Maintenance Instruction

Do not wash the film for 30 days after the installation. Visual changes during this time period are a natural part of the bonding process.

The patented scratch resistant coating on window films is extremely durable. With proper care, your windows will look beautiful for many years to come. For best results, clean your windows with a soft, clean, rubber squeegee or cotton cloth and common household strength glass cleaners, such as Windex®, GlassPlus® or your dealer suggested film cleaner. Avoid using any abrasive cleaners or industrial strength glass cleaners.

To remove tape adhesive or other sticky residue, use Goo Gone.

Depending on the product, it may take up to 60 days for the film to fully cure. Small water spots will diminish and eventually disappear.

If you have any further questions, please call:

PRO-FILM
15 Whippoorwill Lane
Torrington. CT 06790
Tim Van Deusen
1-860-482-3345